



Department of Building & Fire Prevention Bureau

4701 W Russell Rd. • Las Vegas NV 89118
(702) 455-3000 • Fax (702) 221-0630

Ronald L. Lynn, Director/Building & Fire Official * Gregory J. Franklin, Assistant Director
Samuel D. Palmer, Assistant Director * Girard Page, Sr. Deputy Fire Chief

QUALITY ASSURANCE AGENCY MEETING AGENDA

May 21st, 2014

2:00 P.M. – 3:00 P.M.

- **Contact Information – Brian Lenihan**
 - If you have any requests, comments, or need information please email Brian Lenihan at bpl@ClarkCountyNV.gov you can contact Jake Mizrahi at jakem@ClarkCountyNV.gov
- **Interviews – Jake Mizrahi**
 - Jake Mizrahi will be performing the review of inspector approval and interview requests.
- **Fax Notification – Brian Lenihan**
 - Clark County will discontinue the use of fax machines for notification.
 - All correspondences will be sent to the email address on the application.
 - Change in email address for notification will require a revised application.
- **ACI 318-11 – Brian Lenihan**
 - All reports of acceptance tests shall be provided to the licensed design professional, contractor, concrete producer, and, when requested, to the owner and the building official.
- **TG-17 Epoxy Special Inspection – Brian Lenihan**
 - *ACI-I-F and ACI-CCSI certifications will not be accepted for Item X, mechanical or adhesive anchors, after December 31, 2014.
- **Work Plans – Brian Lenihan**
 - All work plans must have the revision paperwork attached and properly filled out.
 - Failure to follow Clark County revision submittal policy could result in delayed review or lost submissions.
- **Item Y – Fire Penetration/Joint special inspections– Brian Lenihan**
 - TRG-Y and P&P will be finalized after the first Item Y permit is completed.
 - Interviews will cover the ASTM's, FCIA Manual of Practice, ESR reports, and industry general practice.
 - International Firestop Council (IFC) provides training documents and a list of references.
<http://www.firestop.org/inspection.html>
- **Enforcement Issues – Brian Lenihan**
 - Work without a permit kills 2 firefighters.
 - Sparks sprayed by welders working on an iron railing caused the fire that tore through a Boston brownstone, killing two firefighters and injuring 13 other people, officials said Friday. Boston Fire Commissioner John Hasson said it did not appear anyone had obtained a permit for work on the railing behind a building attached to the apartment building that burned.
 - Inspector failed to properly sample, test, and document imported fill.
 - Inspector failed to perform adequate density testing on a grading project.
 - County inspector identified deficient welds during site visit. NOV's were issued to fabricator.
- **Public Comment and Discussion**

NOTE: Enter through the North Entrance at the Presentation Room