



Clark County Department of Building & Fire Prevention

Building Division – Inspection Services

Field Inspection Guideline

SUBJECT:	Single Grease Duct Exhaust System	FIG-M-010
Effective Date:	December 10, 1991	Revised: March 10, 2015
		Approved By: BAT
Code Chapter:	2012 UMC Section 510.7.5	Page 1 of 1

Interpretation:

Section 510.7.5 of the Mechanical Code, states the requirements for multiple grease ducts in a single enclosure, in one fire zone, on one floor.

Field Application:

The provision would permit multiple hoods in the same fire area to be served by a single exhaust duct with approval of the AHJ. The Mechanical Code does not permit more than one grease exhaust duct in a grease duct enclosure, because of the hazard of burn through.

Revision History:

Reference #	Title	Effective Date	Revised	Reviewed
FIG-M-010	Single Grease Duct Exhaust System	December 10, 1991		May 31, 2013
FIG-M-010	Single Grease Duct Exhaust System			June 03, 2014
FIG-M-010	Single Grease Duct Exhaust System		March 10, 2015	